

PHY Rate Table Analytics (WiP7500)

From/To	ba:a9:29	Rm210	Rm233	Rm243	Rm218	Rm202	Rm217
ba:a9:29	***	638	655	643	640	634	655
Rm210	633	***	623	646	645	496	649
Rm233	670	645	***	649	640	629	647
Rm243	663	642	641	***	647	643	652
Rm218	630	642	635	645	***	554	652
Rm202	627	500	632	643	558	***	500
Rm217	631	635	631	636	645	491	***

- Low rates indicate dB loss is Greater than 55dB, resulting in intermittent failures
- Look for patterns, the above chart indicates Room 202 has issues
- Focus on Room 202 Coax run, splitters, connectors, wall plates